

Tabulka doporučených elektrocentrál MEDVED pro svařovací invertory ALFA IN a.s.



Kód	Invertory MMA	Příkon [kVA]	Počet fází	V plném rozsahu	Svař. proud do 100A (elektroda do 2,5mm)	Svař. proud do 140A (elektroda do 3,2mm)
5.0272-1	PAN 161	7,7	1	Arctos 8000	Arctos 5000	Arctos 8000
5.0270	PEGAS 160 E Smart	7,4	1	Arctos 8000	Arctos 5000	Arctos 8000
5.0255-1	PEGAS 202 E PFC	7,7	1	Arctos 9000	Arctos 5000	Arctos 8000
5.0254-1	PEGAS 162 E PFC	5,2	1	Arctos 8000	Arctos 5000	Arctos 8000
	Invertory TIG DC					
5.0112-1	PEGAS 160 T HF	7,6	1	ARCTOS 9000 B		
5.0130-1	PEGAS 200 T HF	8,2	1	ARCTOS 9000 B		
5.0161-1	PEGAS 160 T PULSE HF	7,4	1	ARCTOS 9000 B		
5.0176	Alfin 161 W invertor. svářečka	6,4	1	Arctos 9000	Arctos 5000	Arctos 8000
5.0177	Alfin 171 W MAX invertor. svářečka	6,3	1	Arctos 9000	Arctos 5000	Arctos 8000
5.0503	Alfin 300 T invertor. svářečka	13,3	3	Grizzli 16000		
	Invertory TIG AC/DC					
5.0275	Alfin 300 AC/DC invertor. svářečka	14,6	3	Grizzli 16000		
	Invertory multifunkční					
5.0224-1	PEGAS 200 MIG SYN PFC	6,4	1	Arctos 9000	Arctos 5000	Arctos 8000
5.0243-1	PEGAS 200 MIG MAN PFC-1	6,4	1	Arctos 9000	Arctos 5000	Arctos 8000
	AXE 500 IN, AXE 400 IN			GRIZZLI 24000		
	Plasmy					
5.0159-2	PEGAS 40 PLASMA PFC ovo	5,4	1	ARCTOS 9000 B	i s kompresorem do 33A	